PRELIMINARY REPORT ANTATION			NTSB ID: DCA06MA009				Most Critical Injury: Fatal				
			Occurrence Date: 12/08/2005				Investigated By: NTSB				
			Occurrence Type: Accident				ICAO Report Submitted:				
Location/Time											
Nearest City/Place Stat				Zip Code	Local Time	Time Time Zo					
Chicago Midway IL		IL			1915		CST				
Aircraft Information											
Registration Number Aircraft Manufacturer							Model/Series Number				
N471	Boeing						737-700				
Type of Aircraft: Airplane				Homebuilt Aircraft? No							
Injury Summary:	Fatal	1		Serious		Minor	12	Non	е	103	
Sightseeing Flight: No	Air Medical Transport Flight: No										

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

A Southwest Airline B737-700, flight number 1248, slid off the runway at Chicago Midway Airport. The flight was from BWI to Midway. There was snow at the time of the accident. The flight was delayed from leaving BWI due to weather and held for 35 minutes before landing at Midway. Upon landing at Midway the airplane slid of the runway and went through a barrier fence and onto a roadway. There were 98 passengers onboard and 5 crew members on board. An emergency evacuation was done and no injuries have been reported. There are prelim reports of one ground fatality and 12 other ground injuries.

TRANSO_
National Transportation Safety Board
0 7
PRELIMINARY REPORT
7 *** >
AYIATION

NTSB ID: DCA06MA009

PRELIMINARY REPORT AVIATION		Occurrence Date: 12/08/2005								
		Occurrence Type: Accident								
Other Aircraft Involved		•								
Registration Number	Aircraft Manufacturer					Model/Series Number				
Accident Information							<u>'</u>			
Aircraft Damage: Substantial	dent C	Occurred Durin	ng: Lar	nding - roll						
Property Damage:			·							
Crew N	ame				Certificate No.					
Pilot	Pilot									
2										
3										
4										
5	5									
6										
Operator Information Name Operator Designator Code Doing Business As										
Name SOUTHWEST AIRLINES CO	Desig	gnator Code								
Street Address Cit								Zip Code		
-Type of Certificate(s) Held:										
Air Carrier Operating Certificate(s): Flag Carrier/Dor	mestic								
Operating Certificate:					perator Certif	icate:				
Regulation Flight Conducted Under: Part 121: Air Carrier										
Type of Flight Operations Conduc	ted: Scheduled; Do	mestic; l	Passenge	r Onl	у					
Flight Plan/Itinerary										
Type of Flight Plan Filed:										
Last Departure Point					State	Airpor	t Identifier			
Destination					State	Airport	t Identifier	-		
			/ post / do/or							
Weather Information										
Investigator's Source:					Facility ID: Observation Time (Local):					
Sky/Lowest Cloud Condition:					Ft. AGL					
Lowest Ceiling:		Ft. AGL Visibility: SM Altimeter: "I						"Hg		
PRELIMINARY INFORMATION - SUBJECT TO CHANGE									Page 2	

National Transportation Safety Board

NTSB ID: DCA06MA009

PRELIMINARY REPORT									
			Occ	urrence D	Pate: 12/08/2005				
			Occ	urrence T	ype: Accident				
Weather Information		(Continued from page	ge 2)						
Temperature:	°C	Dew Point:	°C	Wind D	Pirection:				
Wind Speed:	Kts.	Gusts:	Kts.	Weathe	er Conditions at Accident S	Site: Instrumer	nt Conditions		
Administration Data									
Notification From						Date	Local Time		
FAA						12/08/2005			
FAA District Office/Coordinator				Investigator-In-Charge (IIC)					
tony james					Robet Benzon				